

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC, Valley Farms/I Pad

Location ID: 335553

Date: 12/31/2024



Dec 31, 2024 at 12:12:20
Silt CO 81652
United States

Location Overview – Photo #05670



Dec 31, 2024 at 12:21:22
Silt CO 81652
United States

Location – Photo #05686

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC, Valley Farms/I Pad

Location ID: 335553

Date: 12/31/2024



Dec 31, 2024 at 12:13:15
Silt CO 81652
United States

Location – Photo #05671



Dec 31, 2024 at 12:15:43
Silt CO 81652
United States

Location – Photo #05673

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC, Valley Farms/I Pad

Location ID: 335553

Date: 12/31/2024



Location – Photo #05672



Location – Photo #05685

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC, Valley Farms/I Pad

Location ID: 335553

Date: 12/31/2024



Trash – Photo #05674




Trash – Photo #05675

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC, Valley Farms/I Pad

Location ID: 335553

Date: 12/31/2024



Trash – Photo #05676



Trash/PRV Discharge Line – Photo #05684

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC, Valley Farms/I Pad

Location ID: 335553

Date: 12/31/2024



Stored Supplies – Photo #05678



Stained Soil – Photo #05683

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC, Valley Farms/I Pad

Location ID: 335553

Date: 12/31/2024



Damaged Tank Insulation – Photo #05682