

**Inspection Photos**  
**Location Name: UYEMURA-67N64W/31SWSE**  
**Location #: 332163**



**Photo #1**  
**Uyemura 34-31 (123-21921) Wellsite**  
**Plugged & Abandoned | PA**  
*Cut / Capped*  
*~ 15 yds.*



**Photo #2**  
**Uyemura 34-31, 33-31,**  
**Pfenning 43-31, 44-31 Battery site**  
**Inactive | Shut-down**  
**Plugged & Abandoned | PA (4-Wells)**  
**Equipment Documented; Fac ID: 488831**



## Inspection Photos

Location Name: UYEMURA-67N64W/31SWSE

Location #: 332163



### Photo #3

Uyemura 34-31, 33-31,  
Pfenning 43-31, 44-31

Battery site

**Inactive | Shut-down**

*Battery entrance*



**COLORADO**

Energy & Carbon Management  
Commission

Department of Natural Resources