

Inspection Photos
Location Name: PFENNING-67N64W/31NESE
Location #: 332495



Photo #1
Pfenning 43-31 (123-22378) Wellsite
Plugged & Abandoned | PA
Cut / Capped
~ 15 yds.



Photo #2
Uyemura 34-31, 33-31,
Pfenning 43-31, 44-31 Battery site
Inactive | Shut-down
Plugged & Abandoned | PA (4-Wells)
Equipment Documented; Fac ID: 488831



Inspection Photos

Location Name: PFENNING-67N64W/31NESE

Location #: 332495



Colorado Energy & Carbon Management Commission
Weld County
+40.522135,-104.589503
50° NE
2024-12-30 15:50

Photo #3

Uyemura 34-31, 33-31,

Pfenning 43-31, 44-31

Battery site

Inactive | Shut-down

Battery entrance



COLORADO

Energy & Carbon Management
Commission

Department of Natural Resources