

**Inspection Photos**  
**Location Name: Sidney Strear 1**  
**Location ID: 317923**



**Photo 1 Location has been cleared of dead vegetation.**



**Photo 2 Stained material has been removed from around the Wellhead.**



**Inspection Photos**  
**Location Name: Sidney Strear 1**  
**Location ID: 317923**



**Photo 3 Well Head sign.**



**Photo 4 Ancillary equipment.**

