

Inspection Photos
Location: Busch 42-30
Location ID: 308588
API # 05-071-08284




Photo 1 –Well placard



Photo 2 – Wellhead

Inspection Photos
Location: Busch 42-30
Location ID: 308588
API # 05-071-08284



Photo 3 – Meter house



Photo 4 – Wellhead and equipment



Inspection Photos
Location: Busch 42-30
Location ID: 308588
API # 05-071-08284



Photo 5 – Back of engine shed, trees removed from back of shed.



Photo 6 – Pit Facility ID 280338, Tree removed from pit

Inspection Photos
Location: Busch 42-30
Location ID: 308588
API # 05-071-08284



**Photo 7 – Hydraulic fitting on wellhead leaking,
stained soils**



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources