

**Inspection Photos**  
**Location: Banchee 41-30 and Banchee 41-30 TR**  
**Location ID: 334234**  
**API # 05-071-06444, 05-071-06736 Tr**



**Photo 1 –Well placard**



**Photo 2 – Original wellhead, Packing leak observed at the time of inspection, White stained soils**



## Inspection Photos

Location: Banchee 41-30 and Banchee 41-30 TR

Location ID: 334234

API # 05-071-06444, 05-071-06736 Tr



**Photo 3 – Pit at 41-30**



**Photo 4 – Pit at 41-30**



**Inspection Photos**  
**Location: Banchee 41-30 and Banchee 41-30 TR**  
**Location ID: 334234**  
**API # 05-071-06444, 05-071-06736 Tr**



**Photo 5 – Leaking packing at 41-30 wellhead**



**Photo 6 – 41-30 Tr wellhead, Leaking packing**

## Inspection Photos

Location: Banchee 41-30 and Banchee 41-30 TR

Location ID: 334234

API # 05-071-06444, 05-071-06736 Tr



**Photo 7 – Pit ID 488312, in process of closure under REM, 37679, Water in pit at the time of inspection.**



**COLORADO**  
Energy & Carbon Management  
Commission  
Department of Natural Resources