

Inspection Photos

January 2nd, 2024

Operator: Simcoe LLC - 10749

Location ID: 325896

Inspection Document #: 714001645

La Plata County, CO

Township: NENW 27 35N 7W N

Corey McDonough - Southwest
Reclamation Specialist



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos
Location Name: Conrad B1
Location ID: 325896



Photo 1. View of well pad taken from the access point facing center.



API #: 067-07138

Inspection Photos
Location Name: Conrad B1
Location ID: 325896



Photo 2. Stormwater BMP/wattles in the eastern portion of the disturbance are filled with sediment and need maintenance.

Inspection Photos
Location Name: Conrad B1
Location ID: 325896



Photo 3. Cut slope remains bare with minimal vegetation.

Inspection Photos
Location Name: Conrad B1
Location ID: 325896



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

Photo 4. Reference area composed of Pine, Oregon Grape and Squirreltail.

API #: 067-07138