

Inspection Photos

January 2nd, 2024

Operator: Simcoe LLC - 10749

Location ID: 306896

Inspection Document #: 714001646

La Plata County, CO

Township: SESW 22 35N 7W N

Corey McDonough - Southwest
Reclamation Specialist



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos
Location Name: Goeglein 2
Location ID: 306896



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

Photo 1. View of check dam stormwater BMPs in the northern portion of the location that appear to be in working order.

API #: 067-08991

Inspection Photos
Location Name: Goeglein 2
Location ID: 306896



Photo 2. View of bare cutslope with minimal vegetation.



Inspection Photos
Location Name: Goeglein 2
Location ID: 306896

1/2/25
106° E



Photo 3. View of stained soils around well head.



Inspection Photos
Location Name: Goeglein 2
Location ID: 306896

1/2/25
56° NE



Inspection Photos
Location Name: Goeglein 2
Location ID: 306896



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

Photo 5. Reference area composed of Pine, Gambel Oak and Squirreltail.

API #: 067-08991