

Inspection Photos

January 2nd, 2024

Operator: Simcoe LLC - 10749

Location ID: 325840

Inspection Document #: 714001647

La Plata County, CO

Township: NWSE 22 35N 7W N

Corey McDonough - Southwest
Reclamation Specialist



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos
Location Name: Goeglein 1
Location ID: 325840



Photo 1. View of the well pad taken from the access point facing center.



Inspection Photos
Location Name: Goeglein 1
Location ID: 325840



Photo 2. Stormwater BMPs on the southern edge of the pad have not been installed or maintained properly. Erosion issues persist and sediment is moving underneath the wattles.

Inspection Photos
Location Name: Goeglein 1
Location ID: 325840



1/2/25
0° N

Photo 3. Failing BMPs is leading to sediment transport into the southern interim reclamation area.

Inspection Photos
Location Name: Goeglein 1
Location ID: 325840

1/2/25
354° N



Photo 4. Sign/placard at separator has deteriorated and is no longer legible.

Inspection Photos
Location Name: Goeglein 1
Location ID: 325840



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

Photo 5. Reference area composed of Pine, Gambel Oak and Squirreltail.

API #: 067-07060