

Inspection Photos

January 2nd, 2024

Operator: Simcoe LLC - 10749

Location ID: 325737

Inspection Document #: 714001648

La Plata County, CO

Township: SWNE 22 35N 7W N

Corey McDonough - Southwest
Reclamation Specialist



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos
Location Name: Huntington A1
Location ID: 325737



Photo 1. View of the well pad taken from the access point facing center.



Inspection Photos
Location Name: Huntington A1
Location ID: 325737

1/2/25
130° SE



Photo 2. View of the eastern interim reclamation area. No stormwater issues observed on location.

Inspection Photos
Location Name: Huntington A1
Location ID: 325737

1/2/25
163° S



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

Photo 3. Reference area composed of Sand Dropseed, Gambel Oak and Pine.

API #: 067-06921