

Inspection Photos

Location: LARAMIE ENERGY LLC GRIFFITH-69S94W/11NWNE (Griffith/11-2 Pad)

Location ID: 334495

Date: 12/31/2024



Photo # 1762 Entrance to location




Photo # 1784 Location

Inspection Photos

Location: LARAMIE ENERGY LLC Griffith/11-2 Pad

Location ID: 334445

Date: 12/31/2024



Photo # 1763 Location



Photo # 1764 Location

Inspection Photos
Location: LARAMIE ENERGY LLC Griffith/11-2 Pad
Location ID: 334445
Date: 12/31/2024



Photo # 1778 Location



Photo # 1779 Location

Inspection Photos

Location: LARAMIE ENERGY LLC Griffith/11-2 Pad

Location ID: 334445

Date: 12/31/2024



Dec 31, 2024 at 12:44:03 PM
+39.295518,-107.845046 ±3.44m
Collbran



Dec 31, 2024 at 1:06:29 PM
+39.294577,-107.844706 ±2.43m
Collbran

Photo # 1783 Location

Photo # 1797 SE corner of location

Inspection Photos

Location: LARAMIE ENERGY LLC Griffith/11-2 Pad

Location ID: 334445

Date: 12/31/2024



Photo # 1798 SW corner of location



Photo # 1799 NW corner of location

Inspection Photos
Location: LARAMIE ENERGY LLC Griffith/11-2 Pad
Location ID: 334445
Date: 12/31/2024



Photo # 1800 NE corner of location




Photo # 1769 Becoming illegible

Inspection Photos
Location: LARAMIE ENERGY LLC Griffith/11-2 Pad
Location ID: 334445
Date: 12/31/2024



Photo # 1770 Becoming illegible

Photo # 1771 Becoming illegible

Inspection Photos
Location: LARAMIE ENERGY LLC Griffith/11-2 Pad
Location ID: 334445
Date: 12/31/2024





Photo # 1785 Inaccurate capacity

Photo # 1788 Showing signs of disrepair

Inspection Photos
 Location: LARAMIE ENERGY LLC Griffith/11-2 Pad
 Location ID: 334445
 Date: 12/31/2024




Photo # 1793 Becoming illegible

