

Inspection Photos

Location: LARAMIE ENERGY LLC McDaniel/2-1 Pad

Location ID: 334353

Date: 12/31/2024



Photo # 1883 Entrance to location



Photo # 1903 Location

Inspection Photos

Location: LARAMIE ENERGY LLC McDaniel/2-1 Pad

Location ID: 334353

Date: 12/31/2024



Photo # 1884 Location



Photo # 1885 Location



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

Inspection Photos

Location: LARAMIE ENERGY LLC McDaniel/2-1 Pad

Location ID: 334353

Date: 12/31/2024



Photo # 1897 Location



Photo # 1898 Location

Inspection Photos

Location: LARAMIE ENERGY LLC McDaniel/2-1 Pad

Location ID: 334353

Date: 12/31/2024



Photo # 1901 Location



Photo # 1919 NE corner of location

Inspection Photos

Location: LARAMIE ENERGY LLC McDaniel/2-1 Pad

Location ID: 334353

Date: 12/31/2024



Photo # 1920 NW corner of location




Photo # 1921 SW corner of location

Inspection Photos

Location: LARAMIE ENERGY LLC McDaniel/2-1 Pad

Location ID: 334353

Date: 12/31/2024



Photo # 1922 SE corner of location




Photo # 1904 Label is peeling