

Inspection Photos  
Location Name: Newbanks 3-14  
API Number: 125-09087



1. Lease sign at well location.



2. View of wellhead.

Inspection Photos  
Location Name: Newbanks 3-14  
API Number: 125-09087



3. Lease sign at remote gathering location.



4. Gas meter inside meter shed.



**Inspection Photos**  
**Location Name: Newbanks 3-14**  
**API Number: 125-09087**



**5. View of produced water tank.**



**6. Remote gathering location overview.**