

Inspection Photos
Location Name: Newbanks 2-14
API Number: 125-07170



1. Lease sign at P&A well location.



2. View of P&A well location.

Inspection Photos
Location Name: Newbanks 2-14
API Number: 125-07170



3. View of P&A well location.



4. Lease sign at remote shared gathering location.

Inspection Photos
Location Name: Newbanks 2-14
API Number: 125-07170



5. Removed equipment site at shared location.



6. View of removed equipment site at shared location.