

Inspection Photos
Location Name: State 16-1
API Number: 125-09156



1. Lease sign at location.



2. Erosion channeling at edge of location.

Inspection Photos
Location Name: State 16-1
API Number: 125-09156



3. Erosion channeling on access trail.



4. Erosion channeling on access trail.

Inspection Photos
Location Name: State 16-1
API Number: 125-09156



5. Erosion channeling on access trail.



6. Erosion channeling on access trail.