

Inspection Photos

API: 071-07180

Operator: OGRIS OPERATING LLC

Inspection Date: 1/3/2025

County: LAS ANIMAS



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos



Photo 1. Facing northwest toward the location.



Inspection Photos



Photo 2. There is a drip leak at the wellhead.



Inspection Photos



Photo 3. There is oily fluid in the engine skid that needs to be cleaned up.



COLORADO
Energy & Carbon Management
Commission

Department of Natural Resources

API:071-07180 | Date: 1/3/2025

Inspection Photos



Photo 4. Facing northeast toward the PW pits..



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

API:071-07180 | Date: 1/3/2025