

Inspection Photos

API: 071-07191

Operator: OGRIS OPERATING LLC

Inspection Date: 1/3/2025

County: LAS ANIMAS



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos



Photo 1. Facing southwest toward the location.



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

Inspection Photos



Photo 3. Facing southwest at the location. The HILL RANCH #9-03 V has been plugged and abandoned and the south side of the location is reclaimed including the associated pit.



COLORADO
Energy & Carbon Management
Commission

Department of Natural Resources

API:071-07191 | Date: 1/3/2025

Inspection Photos



Photo 2. The pit has been backfilled and reclaimed. Soils have been tracked for temporary stabilization.



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources