

# Inspection Photos

API: 071-07192

Operator: OGRIS OPERATING LLC

Inspection Date: 1/3/2025

County: LAS ANIMAS



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources

## Inspection Photos



**Photo 1.** Facing west toward the location.



**COLORADO**  
Energy & Carbon Management  
Commission  
Department of Natural Resources



## Inspection Photos



January 3, 2025  
+37.017058,-104.896699  
Las Animas County  
ECMC

**Photo2.** Facing southwest at the location. The HILL RANCH #9-03 V has been plugged and abandoned and the south side of the location is reclaimed including the associated pit.



**COLORADO**  
Energy & Carbon Management  
Commission

Department of Natural Resources

API:071-07192 | Date: 1/3/2025



## Inspection Photos



**Photo 3.** Well sign is posted at meter shed.





## Inspection Photos



**Photo 4.** There is an area of stained soils that will need clean up.





## Inspection Photos



**Photo 5.** Facing northeast along the fill slope. There are noxious weeds (Mullein) along the fill slope that will need to be controlled.

