

Inspection Photos

Location Name: AURORA USX AB-67N64W/25SESE

Location #: 410103



Photo #1

Aurora USX AB 25-16P (123-30151) Wellsite

Temporarily Abandoned | TA

Emergency contact number barely legible



Photo #2

Aurora USX AB 25-16P, 25-10P, 25-11P Wellsite(s)

Wellsite(s) entrance



COLORADO

Energy & Carbon Management
Commission

Department of Natural Resources

Inspection Photos

Location Name: AURORA USX AB-67N64W/25SESE

Location #: 410103



Photo #3

Aurora USX AB 25-16P, 25-10P, 25-11P Battery site

Abandoned: ALL Equipment Removed

Formerly served:

Aurora - USX AB 25-25;

Plugged & Abandoned | PA



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources