

Inspection Photos

Location Name: AURORA USX AB-67N64W/25NWSE

Location #: 410102



Photo #1

Aurora USX AB 25-10P (123-30150) Wellsite
Temporarily Abandoned | TA



Photo #2

Aurora USX AB 25-16P, 25-10P, 25-11P Wellsite(s)
Wellsite(s) entrance



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Location Name: AURORA USX AB-67N64W/25NWSE

Location #: 410102



Photo #3

Aurora USX AB 25-16P, 25-10P, 25-11P Battery site

Abandoned: ALL Equipment Removed

Formerly served:

Aurora - USX AB 25-25;

Plugged & Abandoned | PA



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources