

## Inspection Photos

Location Name: AURORA - USX AB-67N64W/25NWSW

Location #: 310134



**Photo #1**

**Aurora - USX AB 25-25 (123-25954) Wellsite**

**Plugged & Abandoned | PA**

*Cut / Capped*

*~ 15 yds.*



**Photo #2**

**Aurora USX AB 25-16P, 25-10P, 25-11P Battery site**

**Abandoned: ALL Equipment Removed**

*Formerly served:*

*Aurora - USX AB 25-25;*

*Plugged & Abandoned | PA*



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources