

Inspection Photos

January 2nd, 2024

Operator: Simcoe LLC - 10749

Location ID: 325838

Inspection Document #: 714001664

La Plata County, CO

Township: SESE 8 34N 6W N

Corey McDonough - Southwest
Reclamation Specialist



COLORADO


**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos
Location Name: Morrison Federal 1
Location ID: 325838



Photo 1. View of the well pad taken from the access point facing center.



API #: 067-07058



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

Inspection Photos
Location Name: Morrison Federal 1
Location ID: 325838



Photo 2. Signs/placards at separators have deteriorated and are no longer legible.



1/2/25
239° SW



1/2/25
233° SW



Photo 4. View of hay that remains stored on the southern edge of the pad.

Inspection Photos
Location Name: Morrison Federal 1
Location ID: 325838



Photo 5. Reference area composed of Smooth Brome, Gambel oak and Pine.