

Final Reclamation and Stormwater Inspection

Date: 01/02/2025

Operator: STELBAR OIL CORP INC - 82470

Location ID: 317155

Inspection Document #: 708201895

Washington County, CO



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

Inspection Photos
Location Name: State B #1
Location ID: 317155



Photo 1. Taken southwest of the location, facing southwest along the access road. It does not appear that the access road has been reclaimed. See proceeding photos for additional.

Inspection Photos
Location Name: State B #1
Location ID: 317155



Photo 2. Aerial imagery taken 06/11/1975, approximately 3 years before Well API 121-09383 was spud (12/03/1978), illustrating that the access road does not appear to be in existence prior to oil and gas development. Red circle indicates approximate location of Well API 121-09383; green arrow represents landmark to be used as reference in proceeding photo.

Inspection Photos
Location Name: State B #1
Location ID: 317155



Photo 3. Google Earth aerial imagery (circa 09/2023) illustrating the access road to Well API 121-09383. Red outline illustrates access road that does not appear to have been reclaimed based on observations at the time of this inspection. Green arrow illustrates landmark used for reference with previous photo.

Inspection Photos
Location Name: State B #1
Location ID: 317155



Photo 4. Taken near the southwest corner of the location. Photo illustrates evidence of bare soils within the reclaimed areas.

Inspection Photos
Location Name: State B #1
Location ID: 317155



Photo 5. Taken near the northwest corner of the reclaimed location. Portions of the location appear to be progressing towards reclamation standards.

Inspection Photos
Location Name: State B #1
Location ID: 317155



Photo 6. Taken from the northern portion of the former pit. Reclamation does not appear to be progressing with evidence of non-uniform vegetation cover resulting in bare soils.

Inspection Photos
Location Name: State B #1
Location ID: 317155



Photo 7. Taken near the northeast corner of the reclaimed location. Reclamation does not appear to be progressing with evidence of non-uniform vegetation cover resulting in bare soils.

Inspection Photos
Location Name: State B #1
Location ID: 317155



Photo 8. Taken near the southeast corner of the reclaimed location, near the former well location. Reclamation does not appear to be progressing with evidence of non-uniform vegetation cover resulting in bare soils.

Inspection Photos
Location Name: State B #1
Location ID: 317155



Photo 9. Continued from Photo 8, facing east.

Inspection Photos
Location Name: State B #1
Location ID: 317155



Photo 10. Adjacent reference area photo taken from the former fence line, north of the location.