

## Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC, Frei/A Pad

Location ID: 417777

Date: 12/31/2024



Location Overview – Photo #05689



Location – Photo #05712

# Inspection Photos


Location Name: TEP ROCKY MOUNTAIN LLC, Frei/A Pad

Location ID: 417777

Date: 12/31/2024



Location – Photo #05693



Location – Photo #05699

# Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC, Frei/A Pad

Location ID: 417777

Date: 12/31/2024



Location – Photo #05696



Unused Equipment – Photo #05690

# Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC, Frei/A Pad

Location ID: 417777

Date: 12/31/2024



Unused Equipment – Photo #05691



Wildlife Entry Hazard – Photo #05694

# Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC, Frei/A Pad

Location ID: 417777

Date: 12/31/2024



Dec 31, 2024 at 13:18:31  
New Castle CO 81647  
United States



Dec 31, 2024 at 13:15:24  
New Castle-CO 81647  
United States

Wildlife Entry Hazard – Photo #05695

Wildlife Entry Hazard – Photo #05692

## Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC, Frei/A Pad

Location ID: 417777

Date: 12/31/2024



Open-Ended Load Hose – Photo #05700



Lack of Stabilization – Photo #05698

## Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC, Frei/A Pad

Location ID: 417777

Date: 12/31/2024



**Lack of Stabilization – Photo #05709**



**Insufficient Tracking BMPs – Photo #05713**