

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC, GIBSON GULCH UNIT-66S91W/31NWNW

Location ID: 335290

Date: 12/31/2024



Location Overview – Photo #05715



Location – Photo #05718

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC, GIBSON GULCH UNIT-66S91W/31NWNW

Location ID: 335290

Date: 12/31/2024



Location – Photo #05723



Location – Photo #05725

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC, GIBSON GULCH UNIT-66S91W/31NWNW

Location ID: 335290

Date: 12/31/2024



Dec 31, 2024 at 13:44:14
6051 Divide Creek Rd
New Castle CO 81647
United States

Location – Photo #05722



Dec 31, 2024 at 13:43:11
6051 Divide Creek Rd
New Castle CO 81647
United States

Location – Photo #05719

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC, GIBSON GULCH UNIT-66S91W/31NWNW

Location ID: 335290

Date: 12/31/2024



Open Wellhead Cellar/No Wildlife Egress – Photo #05716



Open Wellhead Cellar/No Wildlife Egress – Photo #05717

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC, GIBSON GULCH UNIT-66S91W/31NWNW

Location ID: 335290

Date: 12/31/2024



Wildlife Entry Hazard – Photo #05724



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources