

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC, GIBSON GULCH UNIT-66S91W/30SWSW

Location ID: 335277

Date: 12/31/2024



Location Overview – Photo #05727



Location – Photo #05728

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC, GIBSON GULCH UNIT-66S91W/30SWWSW

Location ID: 335277

Date: 12/31/2024



Location – Photo #05732



Location – Photo #05734

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC, GIBSON GULCH UNIT-66S91W/30SWSW

Location ID: 335277

Date: 12/31/2024



Location/Unused Equipment – Photo #05735



Dead Weeds Around Wellheads – Photo #05729

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC, GIBSON GULCH UNIT-66S91W/30SWSW

Location ID: 335277

Date: 12/31/2024



Dead Weeds Around Wellheads – Photo #05731



Stored Supplies – Photo #05736

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC, GIBSON GULCH UNIT-66S91W/30SWSW

Location ID: 335277

Date: 12/31/2024



Open-Ended Line/Unused Equipment – Photo #05737



Wildlife Entry Hazard – Photo #05733