

Inspection Photos
Location Name: Lueking 11-30
API Number: 125-07092



1. Lease sign at well location. Sign is down on the ground inside fencing.



2. View of wellhead.

Inspection Photos
Location Name: Lueking 11-30
API Number: 125-07092



3. Well location overview.



4. Lease sign at remote gathering location.

Inspection Photos
Location Name: Lueking 11-30
API Number: 125-07092



5. Gas meter inside meter shed.



6. Remote gathering location overview.