


Inspection Photos  
Location Name: O. Lueking 5  
API Number: 125-06313



1. Lease sign at well location.



2. View of wellhead.

**Inspection Photos**  
**Location Name: O. Lueking 5**  
**API Number: 125-06313**



**3. Power and control panel for removed Pump Jack.**



**4. Gas meter shed.**



**Inspection Photos**  
**Location Name: O. Lueking 5**  
**API Number: 125-06313**



**5. Gas meter inside meter shed.**



**6. Location overview.**