

Inspection Photos
Location Name: C. Korf 2-19
API Number: 125-06977



1. Lease sign at well location.



2. View of wellhead. Note water leg disconnected to resolve previously identified water leak. CA complete.

Inspection Photos
Location Name: C. Korf 2-19
API Number: 125-06977



3. Lease sign at remote gathering location.



4. Gas meter inside meter shed at shared gathering location.