

# Inspection Photos

12/31/2024

**Operator:** WINDSOR ENERGY GROUP LLC

#10081

**Location ID:** 398460

**Inspection Doc:** 718100146

Rio Blanco County, CO

Aaron Trujillo

Western Reclamation Work Lead

ECMC



**COLORADO**


**Energy & Carbon Management  
Commission**

Department of Natural Resources

## Inspection Photos

Operator Name: WINDSOR ENERGY GROUP LLC #10081

Location ID: 398460



**Photo 1:** Limited inspection due to snow cover. Location appears to be predominantly Broom Snakeweed; establishment is largely uniform throughout the site. Material piles (rock/gravel/dirt) remain stockpiled on the Location- trash debris also observed.



**COLORADO**

Energy & Carbon Management  
Commission

Department of Natural Resources