

# Inspection Photos

12/31/2024

**Operator:** WINDSOR ENERGY GROUP LLC

#10081

**Location ID:** 397591

**Inspection Doc:** 718100148

Rio Blanco County, CO

Aaron Trujillo

Western Reclamation Work Lead

ECMC



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources

## Inspection Photos

Operator Name: WINDSOR ENERGY GROUP LLC #10081

Location ID: 397591



**Photo 1:** Limited inspection due to snow cover. Vegetation is not progressing towards a uniform perennial vegetative establishment. Access road has not been reclaimed (gravel/culvert remains, drainage has not been contoured/reclaimed).



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources

## Inspection Photos

Operator Name: WINDSOR ENERGY GROUP LLC #10081

Location ID: 397591



**Photo 2:** Limited inspection due to snow cover. Vegetation is not progressing towards a uniform perennial vegetative establishment. Access road has not been reclaimed (gravel/culvert remains, drainage has not been contoured/reclaimed).



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources