

Inspection Photos

API: 043-06194

Operator: **INCREMENTAL OIL & GAS (FLORENCE) LLC**

Inspection Date: 1/6/2025

County: FREMONT



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos



Photo 1. Drone aerial photo facing south toward the wellsite.



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

Loc:417859 | Date: 1/6/2025

Inspection Photos



Photo 2. Facing down toward the wellsite.



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

Loc:417859 | Date: 1/6/2025

Inspection Photos



Photo 3. Facing back northwest. There is an offsite tank battery shown at red arrow.



Inspection Photos



Photo 4. Facing southwest toward the offsite tank battery which has 6 tanks.



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

Loc:417859 | Date: 1/6/2025

Inspection Photos



Photo 5. It appears a recent truck load out has spilled oil onto the ground at red arrow. The oil stained soils must be cleaned up.



Inspection Photos



Photo 6. Facing toward the east side of the location which consists of undesirable weeds (Kochia). This area of the location must be reseeded.



Inspection Photos



Photo 7. Facing south at the offsite tank battery. The associated well sites are located at red arrow.

