

Inspection Photos

API: 043-06157

Operator: **INCREMENTAL OIL & GAS (FLORENCE) LLC**

Inspection Date: 1/6/2025

County: FREMONT



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos



Photo 1. Drone aerial photo facing southwest overlooking the abandoned wellsite and active tank battery. The highlighted area of the abandoned wellsite has not been reclaimed.



COLORADO
Energy & Carbon Management
Commission

Department of Natural Resources

Loc:334402 | Date: 1/6/2025

Inspection Photos



Photo 2. Drone aerial photo facing east overlooking the abandoned wellsite. Unused areas of the location must be reclaimed.



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

Loc:334402 | Date: 1/6/2025