

Inspection Photos

API: 043-06181

Operator: **INCREMENTAL OIL & GAS (FLORENCE) LLC**

Inspection Date: 1/6/2025

County: FREMONT



Inspection Photos



Photo 2. Facing back northeast toward the location.



Inspection Photos



Photo 2. A spill occurred at the tank and impacted soils must be cleaned up.



Inspection Photos



Photo 3. Facing toward the wellsite.

