

Final Reclamation and Stormwater Inspection

Date: 01/07/2024

Operator: PDC ENERGY INC - 69175

Location ID: 464272

Inspection Document #: 708201910

Weld County, CO



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

Inspection Photos
Location Name: Briggs TB
Location ID: 464272



Photo 1. Screenshot from the drone closure report (doc #404013669; Page 13) indicating that the access road off of US 34 has been reclaimed. Based on review of the closure report, it does not appear that the access road has been reclaimed.

Inspection Photos
Location Name: Briggs TB
Location ID: 464272



Photo 2. Screenshot from the drone closure report (doc #404013669; Page 18) illustrating that the former access road to the tank battery does not appear to have been reclaimed.



Photo 3. Google Maps imagery (reportedly from May 2024) illustrating that the former tank battery access road off of US 34 does not appear to have been reclaimed with evidence of road base material, culvert and contouring/grading that is not reflective of the adjacent areas.