

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC, Furr/F-03 Pad

Location ID: 335021

Date: 1/7/2025



Location Overview – Photo #05815



Location – Photo #05810

Inspection Photos


Location Name: TEP ROCKY MOUNTAIN LLC, Furr/F-03 Pad

Location ID: 335021

Date: 1/7/2025



Insufficient Wildlife Protection – Photo #05812



Insufficient Wildlife Protection – Photo #05814