

# Inspection Photos

Loc: 428957

Operator: WINN EXPLORATION CO INC

Inspection Date: 1/6/2025



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources

## Inspection Photos



**Photo 1.** Drone aerial photo facing southwest toward the location.



## Inspection Photos



**Photo 2.** There are still degraded perimeter wattles that have not been removed.



## Inspection Photos



**Photo 3.** Facing west at the location. It appears the perennial vegetation is progressing throughout the location.



## Inspection Photos



**Photo 4.** Facing northwest. There is still a gravel pile that remains.

