

## Inspection Photos

Location Name: MONFORT-65N63W/30NWSW

Location ID: 330198



**Photo #1**

**Monfort BB 30-12 Battery site**

**Inactive | Shut-down**

*Wellsite(s), Battery entrance*



**Photo #2**

**Monfort BB 30-12 Battery site**

**Inactive | Shut-down**

*Formerly served:*

*Monfort BB 30-11, 30-13, 30-14;*

*Plugged & Abandoned | PA*



**COLORADO**


**Energy & Carbon Management  
Commission**

Department of Natural Resources

## Inspection Photos

Location Name: MONFORT-65N63W/30NWSW

Location ID: 330198



**Photo #3**

**Monfort BB 30-12 Battery site**

**Inactive | Shut-down**

*Crude oil, produced H<sub>2</sub>O tank(s): SE corner*



**Photo #4**

**Monfort BB 30-12 Battery site**

**Inactive | Shut-down**

*ECD(s), Separator(s)*



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources

**Inspection Photos**  
**Location Name: MONFORT-65N63W/30NWSW**  
**Location ID: 330198**



**Photo #5**  
**Monfort BB 30-12 Battery site**  
**Inactive | Shut-down**  
*Battery sign*



## Inspection Photos

Location Name: MONFORT-65N63W/30NWSW

Location ID: 330198

Associated Well(s)	API	Status
1. Monfort BB 30-12	123-18607	TA

### Photo #6

Monfort BB 30-12 Battery site

Inactive | Shut-down

Associated Well(s):

1: Temporarily Abandoned | TA



**COLORADO**

Energy & Carbon Management  
Commission

Department of Natural Resources