

Final Reclamation and Stormwater Inspection

Date: 01/08/2025

Operator: NOBLE ENERGY INC - 100322

Location ID: 322808

Inspection Document #: 708201917

Weld County, CO



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

Inspection Photos
Location Name: SLW Ranch 1-10
Location ID: 322808




Photo 1. Screenshot taken from the drone closure report (Page 13; doc #404016974) illustrating overview of the land use change and disturbance areas.

Inspection Photos
Location Name: SLW Ranch 1-10
Location ID: 322808



Photo 2. Screenshot taken from the drone closure report (Page 15; doc #404016974) illustrating overview of the land use change and disturbance areas. Midstream equipment (circled in red) near the former tank battery facility.