

Inspection Photos

Location Name: QB Energy SAVAGE 1-14 (RA1) Pad

Location #: 334747



Photo # 7332 From entrance to location



Photo # 7333 Location



Inspection Photos
Location Name: QB Energy SAVAGE 1-14 (RA1) Pad
Location #: 334747



Photo # 7334 Location



Photo # 7335 Location

Inspection Photos
Location Name: QB Energy SAVAGE 1-14 (RA1) Pad
Location #: 334747



Photo # 7336 Location



Photo # 7337 Location

Inspection Photos

Location Name: QB Energy SAVAGE 1-14 (RA1) Pad

Location #: 334747



**Photo # 7338 Flowline heating insulation open ended
/wildlife hazard/available for entry by wildlife**



**Photo # 7339 Burner tube missing cap/open ended/wildlife
hazard/available for entry by wildlife**