

## Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC, FURR/22-15A

Location ID: 413541

Date: 1/7/2025



Location Overview – Photo #05817



Location – Photo #05833

# Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC, FURR/22-15A

Location ID: 413541

Date: 1/7/2025



Location – Photo #05818



Location – Photo #05819

## Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC, FURR/22-15A

Location ID: 413541

Date: 1/7/2025



Location – Photo #05824



Location – Photo #05821

# Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC, FURR/22-15A

Location ID: 413541

Date: 1/7/2025



Jan 7, 2025 at 12:11:56  
Parachute CO 81635  
United States



Jan 7, 2025 at 12:09:40  
Parachute CO 81635  
United States

Location – Photo #05832

Peeling Tank Label – Photo #05822