

Inspection Photos
Location Name: 70 Ranch USX BB/35-01P
Location #: 415988



Photo #1

70 Ranch USX BB 35-01P (123-31283) Wellsite
Temporarily Abandoned | TA



Photo #2

70 Ranch USX BB 35-08, 35-01P Wellsite(s)
Wellsite(s) entrance



Inspection Photos

Location Name: 70 Ranch USX BB/35-01P

Location #: 415988



Photo #3

70 Ranch USX BB 35-08, 35-01P Battery site

Abandoned: ALL Equipment Removed

Formerly served:

70 Ranch USX BB 35-02;

Plugged & Abandoned | PA



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources