

# Final Reclamation and Stormwater Inspection

December 31, 2024

Operator: KERR MCGEE OIL & GAS ONSHORE LP - 47120

Location ID: 320246

Well Name: SELTZER FARMS #A 4

Inspection Document #: 718600138

Adams County, CO

Anthony Dunnam  
Reclamation Specialist, ECMC



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources

Inspection Photos  
Location Name: SELTZER FARMS #A 4  
Location ID: 320246



**Photo 1.** Overview of location from the northeast corner looking southwest. No equipment remains on site. Evidence of decompaction activity. Undesirable annual Kochia is present throughout the site. Site has been mowed to control weeds. Perennial crop forage has not established.



**Photo 2.** Looking north from well location. See Photo 1 comments.

Inspection Photos  
Location Name: SELTZER FARMS #A 4  
Location ID: 320246



**Photo 3.** Looking east from well location. See Photo 1 comments.



**Photo 4.** Looking south from well location. See Photo 1 comments.

Inspection Photos  
Location Name: SELTZER FARMS #A 4  
Location ID: 320246



**Photo 5.** Looking west from well location. See Photo 1 comments.



**Photo 6.** Looking south along access road. Access road was preexisting to oil and gas activity.



Inspection Photos  
Location Name: SELTZER FARMS #A 4  
Location ID: 320246



**Photo 7.** Historic aerial imagery taken 08/16/1978. Access road appears to be preexisting to oil and gas (red arrow is access road, green circle is approximate well location).

