

# Inspection Photos

January 7th, 2024

Operator: High River Resources Operating - 10734

Location ID: 325264

Inspection Document #: 714001669

La Plata County, CO

Township: NWNW 20 32N 7W N

Corey McDonough - Southwest  
Reclamation Specialist



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources



Inspection Photos  
Location Name: Ute 3  
Location ID: 325264



Photo 1. View of wellhead assembly.



API #: 067-06026



**COLORADO**  
Energy & Carbon Management  
Commission  
Department of Natural Resources



Inspection Photos  
Location Name: Ute 3  
Location ID: 325264



**COLORADO**  
Energy & Carbon Management  
Commission  
Department of Natural Resources

**Photo 2.** Impacted surface material has been removed at active equipment.

API #: 067-06026



Inspection Photos  
Location Name: Ute 3  
Location ID: 325264



**COLORADO**  
Energy & Carbon Management  
Commission  
Department of Natural Resources

**Photo 3.** Stormwater BMPs installed in the eastern cutslope area. Vegetation is progressing in this area.

API #: 067-06026



Inspection Photos  
Location Name: Ute 3  
Location ID: 325264



**COLORADO**  
Energy & Carbon Management  
Commission  
Department of Natural Resources

**Photo 4.** Western interim reclamation area composed of Sand Dropseed, Sagebrush and Rubber Rabbitbrush.

API #: 067-06026



