

# Inspection Photos

January 7th, 2024

Operator: Simcoe - 10749

Location ID: 333123

Inspection Document #: 714001670

La Plata County, CO

Township: SENE 17 32N 7W N

Corey McDonough - Southwest  
Reclamation Specialist




**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources

Inspection Photos  
Location Name: Knight GU  
Location ID: 333123

1/7/25  
279° W



**Photo 1.** View of well pad taken from the access point facing center.





**Photo 2.** Gully erosion forming at location access point.



Inspection Photos  
Location Name: Knight GU  
Location ID: 333123

1/7/25  
239° SW



**COLORADO**  
Energy & Carbon Management  
Commission  
Department of Natural Resources

**Photo 3.** View of weedy Kochia/Russian thistle debris on the active pad.

API #: 067-05076, 07842



Inspection Photos  
Location Name: Knight GU  
Location ID: 333123



**COLORADO**  
Energy & Carbon Management  
Commission  
Department of Natural Resources

**Photo 4.** Impacted surface material observed at well head B1.

API #: 067-05076, 07842







Inspection Photos  
Location Name: Knight GU  
Location ID: 333123



**COLORADO**  
Energy & Carbon Management  
Commission  
Department of Natural Resources

**Photo 6.** Reference area composed of Juniper, Sand Dropseed, Broom Snakeweed and Sagebrush.

API #: 067-05076, 07842