

Inspection Photos

January 7th, 2024

Operator: Simcoe - 10749

Location ID: 333832

Inspection Document #: 714001671

La Plata County, CO

Township: SWNE 8 32N 7W N

Corey McDonough - Southwest
Reclamation Specialist



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos
Location Name: Wirt
Location ID: 333832



Photo 1. View of well pad taken from the access point facing center.



API #: 067-05131, 07868





Photo 2. View of weedy debris that remain in large patches on the location.



Inspection Photos
Location Name: Wirt
Location ID: 333832

1/7/25
269° W



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

Photo 4. Southern interim reclamation area composed of Sand Dropseed, Indian Ricegrass and Rubber Rabbitbrush.

API #: 067-05131, 07868

Inspection Photos
Location Name: Wirt
Location ID: 333832

1/7/25
211° SW



Photo 6. Reference area composed of predominantly Sagebrush and Indian Ricegrass.