

Inspection Photos

January 7th, 2024

Operator: Simcoe - 10749

Location ID: 326326

Inspection Document #: 714001672

La Plata County, CO

Township: NENE 7 32N 7W N

Corey McDonough - Southwest
Reclamation Specialist



COLORADO


**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos
Location Name: Snook C1
Location ID: 326326



Photo 1. View of well pad taken from the access point facing center.



API #: 067-07843



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

Inspection Photos
Location Name: Snook C1
Location ID: 326326



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

Photo 2. View of surface owner cage that remains stored in the western portion of the disturbance.

API #: 067-07843

Inspection Photos
Location Name: Snook C1
Location ID: 326326




Photo 3. View of weedy Kochia debris at the center and lining the active pad.

Inspection Photos
Location Name: Snook C1
Location ID: 326326

1/7/25
258° W



Inspection Photos
Location Name: Snook C1
Location ID: 326326



Photo 5. Label at separator is starting to deteriorate but still legible, future maintenance is advised.