

# Inspection Photos

January 7th, 2024

Operator: Simcoe - 10749

Location ID: 334013

Inspection Document #: 714001673

La Plata County, CO

Township: NENE 7 32N 7W N

Corey McDonough - Southwest  
Reclamation Specialist



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources

Inspection Photos  
Location Name: Snook GU C  
Location ID: 334013



1/7/25  
52° NE



1/7/25  
38° NE

Photo 1. View of well pad taken from the access point facing center.

Inspection Photos  
Location Name: Snook GU C  
Location ID: 334013



**COLORADO**  
Energy & Carbon Management  
Commission  
Department of Natural Resources

**Photo 2.** Southern interim reclamation area composed of Western Wheatgrass, Smooth Brome and Sand Dropseed.

API #: 067-09699, 09700

Inspection Photos  
Location Name: Snook GU C  
Location ID: 334013



**COLORADO**  
Energy & Carbon Management  
Commission  
Department of Natural Resources

**Photo 3.** Stormwater BMPs have been installed in the eastern portion of the disturbance.

API #: 067-09699, 09700

Inspection Photos  
Location Name: Snook GU C  
Location ID: 334013



1/7/25  
83° E



**COLORADO**  
Energy & Carbon Management  
Commission  
Department of Natural Resources

**Photo 4.** Reference area composed predominantly of Intermediate Wheatgrass and Rubber Rabbitbrush.

API #: 067-09699, 09700