

# Inspection Photos

January 7th, 2024

Operator: Simcoe - 10749

Location ID: 325048

Inspection Document #: 714001674

La Plata County, CO

Township: NENE 7 32N 7W N

Corey McDonough - Southwest  
Reclamation Specialist



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources

Inspection Photos  
Location Name: Snook A1  
Location ID: 325048



Photo 1. View of well pad taken from the access point facing center.



API #: 067-05139





Inspection Photos  
Location Name: Snook A1  
Location ID: 325048





Inspection Photos  
Location Name: Snook A1  
Location ID: 325048





Inspection Photos  
Location Name: Snook A1  
Location ID: 325048



**Photo 4.** Large patches of weedy Kochia and Russian Thistle debris remains on location.



Inspection Photos  
Location Name: Snook A1  
Location ID: 325048



**COLORADO**  
Energy & Carbon Management  
Commission  
Department of Natural Resources

**Photo 5.** Interim reclamation area composed predominantly of Sagebrush and Rubber Rabbitbrush.

API #: 067-05139



Inspection Photos  
Location Name: Snook A1  
Location ID: 325048



**COLORADO**  
Energy & Carbon Management  
Commission  
Department of Natural Resources

**Photo 6.** Reference area composed predominantly of Sagebrush, Juniper and James Galleta.

API #: 067-05139