

Inspection Photos

January 7th, 2024

Operator: Simcoe LLC - 10749

Location ID: 325080

Inspection Document #: 714001676

La Plata County, CO

Township: NWSE 36 33N 8W N

Corey McDonough - Southwest
Reclamation Specialist



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos
Location Name: Wirt B1
Location ID: 325080



Photo 1. View of location taken from the center facing northwest. Location has been mowed to manage encroachment of vegetation on active equipment.



Photo 2. Label at separator has deteriorated and is no longer legible.